

GENERAL Information

Care and Maintenance

Painted Steel

The polyurethane painted finish does not require special maintenance. Regular dusting with a soft cloth or duster is usually sufficient. If a cleaning agent seems to be necessary, we suggest your using a mild detergent spray. We recommend you treat painted surfaces as you would the paint on your car. Never use any solvent based cleaners. This includes any of the alcohol based cleaners.

Aluminum

Wash aluminum with a small amount of mild soap and a clean cloth with plenty of water.

PLANTERS - We recommend installing a liner in each planter to prevent the metal from reacting to any potential chemicals from fertilizers or chemicals, etc.

Stainless Steel

Wash stainless steel with soapy water, or a mild detergent, thoroughly rinse with clean water and polish with a soft dry cloth.

We recommend you treat the 3R Lids and 7R Tops silk screened ink surface as you would the paint on your car. Never use any solvent based cleaners. This includes any of the alcohol based cleaners and stainless steel cleaners.

Polycarbonate Multi-wall

A mixture of water and mild soap applied with a soft sponge or microfiber cloth to avoid scratching, clean with water and dry with soft dry cloth.

Leather

Leather is a natural material; due to its characteristics, scratches and marks may appear on the surface over time. This appearance is the "character" of natural leather. To maintain the leather, gently dust surface area regularly with a soft, dry cloth. To clean, dampen a clean cloth with lukewarm water. Cleanse the entire area where stain occurred, working from the perimeter of the stain to the center. DO NOT use saddle soap, oil, abrasive, furniture polish, varnish or ammonia.

Plastic Laminate

To clean the surface, use a damp cloth or sponge and a mild soap or detergent. EKITTA recommends obtaining current detailed care and maintenance information directly from the plastic laminate manufacturer.

Wood

EKITTA wood products are protected by a stain-resisting finish. For normal cleaning, wipe surface with a soft, damp (not wet) cloth.